

ATTACHMENT A

**NORTH BAJA PIPELINE EXPANSION PROJECT
A-Line (2001) and B-Line (2005) KOP PHOTOS**

KOP 1. Highway 78 at Milpitas Wash looking east-northeast (MP 35.8)



2001 Visual Conditions Before Pipeline Construction



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 2. Highway 78 at Milpitas Wash looking south-southeast (MP 36.1)



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 3. Highway 78 at Milpitas Wash Looking South-Southeast (MP 36.6)



2001 Visual Conditions Before Pipeline Construction



2005 Visual Conditions After Pipeline Construction and Landscape Restoration

KOP 4. Highway 78 near Access Road IMCA-1009 Looking Due East (MP 39.0)



2001 Visual Conditions Before Pipeline Construction.



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 6. Highway 78 Looking Southeast (MP 42.2)



2001 Visual Conditions Before Pipeline Construction.



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 6. Highway 78 near Access Road IMCA-1037, Looking East-Northeast (MP 47.3)
2001 Visual Conditions Before Pipeline Construction.



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 7. Highway 78 North of the U.S. Border Patrol Checkpoint Station looking Northeast
(MP 47.6)



2001 Visual Conditions Before Pipeline Construction.



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.

KOP 8. Highway 78 South of the U.S. Border Patrol Checkpoint Station Looking East-Northeast
(MP 48.3)



2001 Visual Conditions Before Pipeline Construction.



2005 Visual Conditions After Pipeline Construction and Landscape Restoration.